



Offset – turn the brass screw clockwise to STOP the motor from creeping or moving; turn until the motors stops humming (making noise); it is necessary to have power to the motor control in order to adjust this parameter.